



endble - to make able is fig. (1). shows the main features of plunger - type dial gauge indicator. in The main scale is greeduated into equal divisions corresponding to a 0,01. movement of the plunger.

iii) A second but small dial is set in the main dial face to Indicate the number of completed revolutions turne through one sevolution being equivalen to 1mm & plunger movement. iv) To enable the instrument to be zero for any convenient position, the main scale can be rotated & locked into place, using the scale locking s The principle of operation of the instrument is shown in tiges. · The plunger is attached to a rack. · Meshing with a gear wheel, the str converted into an angular or turni.
motion, the movement being magnif by using a large gear in mesh wo a small gear wheel. . It is the small gear wheel that fitted to the main scale pointer. fig: (3) shows a dial gauge indicator fitted to a pillar stand; the stund enables the indicator to be locked in any required position.






drum of radius 's' attached to the pointe If the pointer is of length R,
the second stage of magnification is R and total maynification, M= 1 XR 1 -> Effective length of 40m

a -> Distance from hinge pivot to knife e


R -> Length of pointer

8 -> Drum readius Advantages: - .

i) It has got a bold scale and large indicator pointer. Disadvantages; -> i) Due to motion of the parts, there is wear in the moving parts.



29 as a bell count lever elbow acts causes twisted strip to change it's longth thus making it further juist or unjuist. Thus the pointer at the centre of
the twisted strip rotates by an amount
proportional to the change in langth of
strip and proportional to the plunger movement -The length of cantilerer can be varied to adjust the magnification of the instrume



gives a reading of dy' on the scale. 1) The magnification takes place through both mechanical and optical methods. The salient features of an optical comparator are; · No wear & fear as there are few moving linkages. · high accuracy due to weightless option lever, little friction & inestia effects · Electrical Supply needed to operate the light gource. in a dark room particularly when the scale is projected onto a screen. have very high magnification Las brall namber of Comporal neving as Congared to rederical compared - Thence occaming ishiples @ Steelie Supply is regressery a the Component used is lange and enpersive.

Electrical comparator; · These comparators are also known as "electro - mechanical mousuring system" as these employ an electromechanical device which converts a mechanical displacement into in electrical input signal. Electro - mechanical measuring system; Fig. Shows block diagram of an elementary electro-mechanical measuring system. The most popular electron-machanical device used to convert mechanical displacement into electrical signal is Linear variable differential fransformer CLV DTJ. Electri- signal lechanical Electrotransducer. Signal conditioning observer lisplacement · LVDT is consist of three symmetrically spaced coils wound on a insulated bobbin. · It works on mutual inductance principle. · The primary care wound on insulating form (bobbin) and two sidentical secondaries symmetrically spaced from the primory. · Ac current is applied to the primary and two secondaries are connected externeuly in a series operation circuit. There is a magnetic core which


nermatic comparator The measurement is done with the relp of compressed wire. Either air flow or air pressure variation is used to measure deviation from standard or reference dimension. 1) The flow or column type comparator! Fig. 1) shows a pneumatic comparator based on measurement of the change in the rate of flow, Bleed to atmosphers. for zero adjustment. 200 adjustment Tapered tube scale. Ploat 1 pegulator. 14 hets Pilter. Fig: 1) Flow or column type wir gauge. . The air has passed through a filter and a regulator, it is is upplied to the gauge at about 70 kpa. · The dir flows through a uniformly tapered glass tube in which a float is suspended by this wis flow. The float is provided with vanes to rotale and give it's stubility.


The top of the tube is connected to the garging head by a plastic tube.

N. A. C.
= 35
The air flowing through the gauge exhall through the passages in the gauging
head into the clearance bet the head
end the work piece.
The rate of flow is propostional to the
- clearance indicated by the position
- floct in the column.
If the hole in the workpiece is
larger than the hole size of the master,
have air flow through the eauylay
in the tube.
conversely, if the hole is sincular thu.
the master, the float will full in
the tube.
2) pressure type comparator: -p.
Air supply.  at constant  pressure.
pressure.
Ps Ps
a posifice.
F Pb
me sence
gauge.
× I
A Direct
A Block
Fig. 2) préssure type air gauge
Fig: 2) pressure type air gauge

Autorcollamolator + DE P · An -autocollimator is an inspumer dosigned to measure small angular displacement and may be used conjuction with a plane mirror or other reflecting surfaces. An autocollimeter Ss essentially an infinity telescope & a collimator d'embined into one instrument. inuple. An autocollinator is based on principle that a columning lens can project and receive a parallel beam light and the reflected bean light will change it's direction bo changing the angle of the surface reflecting the trust The autocollimator's principle 19 Shown In figure Rocal Plancel Collimating lens incident ray reflection Principle g autocollisnator


is suppose a ray goldight is emitted at the middle of from source 's' the focal plane golcollimating lens! is the leng with convert this into q paralel been which is then reflected as CD ... 2000 parties parties, such is If (D' 115 inclined at an angle 'Q', the reflected beam will change it's path at twice the engle of i.e. 20 iv) The lasted lobe am the enters the collimating lens its be focussed at some new point of the focal plane Such as T v) Distance h' is proportional to the angle and medsurement of hi in plane AB lenables values of small angles to be defermined out & vi) It may be noted that the position y the final/ image (h) does not depend upon the distance of reflecter from the lens ice separation on! is from the lens. But if reflector is mored too much back then reflected rays will complet miss the lens and no image will be formed. Thus, for full formings 8400g of readings of instrument to be us
the maximum remoteness of the reflector is limited. 1 = 2xfx01





The main pents of the
The main parts of the toolmaker's microscope.
1) Rotatable table 5> Projection screen.
2) Meaguring stage 6) Micrometers.
3> swinguble head 7> objective lens
A) ocular 8/ Prism.
Civis I
construction: -
if the toolmaker's microscope consists of a
rigid stand on which a swingable head is
mounted.
is) The measuring stage moves on ball guideway.
by actualing two measuring micrometers
arranged perpendicular to each other in
the length and the cross-sections.
in the measuring range of each micrometer
is 25 mm and the measuring capacity
iv) A notatuble tuble is provided over the
stage on which the workpiece can be fixed
stage, on which the workpiece can be fixed either directly or between centres.
vy This twole can be votated through 360°.
Working:-
is The component being measured is illuminated
by the through light method.
i) A parallel beam y light illuminates
the lower side of workpiece which is then
the lower side of workpiece which is then received by the objective lens in it's
way to a prism that deflects the
light rays in the direction of the

measuring ocular and the projection screen. us Incident illumination can also be provided by an expre attachment. iv) Exchangeable objective long having maynification 1x, 1.5x, 3x & 5x are available so that a total magnification of 10x, 15x 1 30x & 50x can be achieved with an ocular of 10x. The direction of illumination can be filted with vespect to the workpiece by filting the measuring head and the whole optical system vi) This inclined illumination is necessary is some cases as in screw thread measurement



Scanned by CamScanner

The main objective lens is interchangeable, giving a magnification range X10, X25, X30, X60, X100 and X200. The graticule also is interchangeable to cater for linear, angular, radial and thread form inspection. The tool makers' microscope, although capable of inspecting any component shape that can be accommodated by optical projectors, is best suited to relatively small, intricate components and tools.

# 3.3 Optical Projectors

The optical projector is a versatile and indispensable instrument in the metrology laboratory. The projector may be used to check the components which are otherwise difficult to do so due to typical of their size, material and dimensional characteristics. The instrument displays the magnified images of the objects located on the working platform - on an appropriate viewing screen. The magnified image serves as an aid to more precise determination of dimension, form, etc.

## The optical system of a projector consists of

- 1. a projector light source and condenser
- 2. suitable work holding table either fixed or movable
- 3. projection optics mirrors and lenses
- 4. screen for viewing the image and checking is made possible
- 5. measuring devices precise mechanical system of measuring aids.

# The following measurement techniques are employed on optical projectors

- 1. measurement by comparison
- 2. measurement by movement table travel and measuring facilities must be available.
- 3. measurement by translation special tracer accessories are required.

# 3.3.1 Nikon optical profile projector

Optical measuring instruments offer a number of advantages over mechanical instruments and provide suitable alternative. These are preferred when contact measurement cannot be used, as in the case of the fragile components or when the shape is highly complex or object is too small. In contrast to the optical comparator which employs an optical system to magnify the movement of a measuring probe, optical measuring instruments use a system of lenses to give a magnified image of the object. The use of light as a means of measurement

can often involve a level of accuracy which cannot be achieved by mechanical instruments. A beam of light is unaffected by distortion and temperature variation although it is dependent on the quality of the optical system.




Fig. 3.3 Profile projector (Optical system)

Figure 3.3 shows Nikon profile projector which has swiveling turret above the stage for mounting the projection lenses. This enables different magnifications to be selected fairly rapidly. The illumination can be switched from shadow to surface by a selector on the front of the instrument. The hand wheel on the right hand side will raise or lower the stage and hence position a component placed on it at the focal point of the lens.

A sliding hood can be positioned to prevent extraneous light shining on the screen. From the above figure it can be seen that, when used for shadow illumination, object placed on it. Alternatively, when surface illumination is selected, the light strikes a half reflecting mirror placed below the projection lens, which reflects it

Whichever means of illumination is used, the image is projected by the lens via the two mirrors in the upper part of the instrument, on the screen.

All objects are not suitable for placing directly on the stage. Awkwardly shaped objects can be mounted between the centers. The stage can be moved on its longitudinal and transverse direction and the movement is controlled by micrometers which have a vernier resolution down to 0.001 mm.

designed on one of the two basic principles: One involves the use of a spirit level and the other makes use of the plumb-bob (or pendulum) principle and works from the vertical.

Clinometers are used for checking angular faces, and relief angles on large cutting tools and milling cutter inserts. These can also be used for setting inclined table on jig boring machines and angular work on grinding machines etc.

The different types of clinometers available are:

- 1. Vernier clinometer
- 2. Micrometer clinometer
- 3. Dial clinometer
- 4. Pendulum clinometer
- 5. Optical clinometer.

The most commonly used clinometer is of Hilger and Watt type. The circular glass scale is totally enclosed and is divided from 0° to 360° at 10' intervals. Sub-division of 10' is possible by the use of an optical micrometer. A coarse scale figured every 10 degrees is provided outside the body for coarse work and approximate angular reading. In some instruments worm and quadrant arrangement is provided so that reading upto 1' is possible.

In some clinometers, there is no bubble but a graduated circle is supported on accurate ball bearings and it is so designed that when released, it always takes up the position relative to the true vertical. The reading is taken against the circle to an accuracy of one second with the aid of vernier.

#### 4.4.1.2.8. Plain index centre

Fundamentally index centres were meant for use on milling machines but they are now being used for inspection work also. This is specially suited to those problems which involve the measurement of a large number of angular dimensions about a common centre. The work is set between the centres and correct angular dimensions are set directly from the indexing plate.

To obtain wide range of angles the following types of indexing methods may be employed:

- 1. Single indexing
- 2. Differential indexing
- 3. Compound indexing.


# 4.4.1.2.9. Optical instruments for angular measurement

Autocollimator. An autocollimator is an instrument designed to measure small angular deflections and may be used in conjuction with a plane mirror or other reflecting surface. An autocollimator is essentially an infinity telescope and a collimator combined into one instrument.

An autocollimator is based on the principle that a collimating lens can project and receive a parallel beam of light and that the reflected beam of light will change its direction by changing the angle of the surface reflecting the light.

The Autocollimator's principle is shown in Fig. 4.88. It shows the collimator lens that projects a parallel beam of light along the optical axis of the system when the light source (electric bulb) is placed at the focus of the collimator lens. A reflector, which can be a slip guage block, an optical flat or a mirror is attached to the surface under rest. If this reflection is accurately normal to the optical axis, the effected beam will return along its original incident path back to the lens and will be collected at a point 'p' exactly at the length of the lens where cross-wires are placed. Therefore the image of the cross wires formed by the reflected light

213






Fig. 4.88. Principle of autocollimator.

beam will, in this case coincide with the cross-wires at point 'p'. If the reflection is slightly tilted at an angle  $\theta$ , the reflected beam will change its path at twice the angle  $\hat{\theta}$ . The reflected beam will, therefore, form an image 'q' at the cross-wires at distance 'pq', the value of which is a measure of the angular deflection  $\theta$ , where  $pq = 2f \cdot \theta$ .

It may be noted that the position of the final image does not depend upon the distance of reflector from the lens, i.e., separation 'd' is independent of the position of reflector from the lens. But if reflector is moved too much back then reflected rays will completely miss the lens and no image will be formed. Thus, for full range of readings of instrument to be used, the maximum remoteness of the reflector is


For high sensitivity, i.e., for large value of 'd' for small angular deviation  $\theta$ , a long focal length is

### Hilger angle dekkor:

Fig. 4.89 shows a typical auto-collimator-the Hilger Angle Dekkor, the description of which is given below:

- It consists of a tubular body containing the collimating lens at one end and viewing eye piece at the other end.
- At the focal plane of the collimating lens, there is a scale instead of cross-wires which is illuminated by means of an electric lamp mounted by the side.
- The eye piece is provided with a fixed scale similar to and at right angles to the illuminated one.

Both scales are divided from 0 to 40 and each division represents 1' of arc.



ANGULAR AND TAPER MEASUREMENTS

# Photo-electric micro-optic auto-collimator

Photo-electric setting makes measuring and checking by auto-collimator far simpler and faster. Micrometer adjustment is provided for setting but coincidence of setting graticule and target image is detected photoelectrically, and shown on a meter as a null reading. This provides a high degree of sensitivity and repeatability, also reducing eye fatigue to a minimum. The eyepiece is normally only used to assist in initial setting up.

The photo-electric auto-collimator is particularly suitable for calibrating polygons, for checking angular indexing and for checking small linear displacements.

Application of auto-collimator. The auto-collimator can be used for measurement of angles of surfaces which are of reflective nature. Thus newly machined and polished surfaces will reflect. In case the surface does not reflect then a parallel slip gauge is wrung to the surface. Fig. 4.91 shows the use of auto-collimator to compare the angle of a precision angle plate with that between two faces of an eight-edged reference plane:




Fig. 4.91. Use of auto-collimator.

- The instrument is firmly fixed in position relative to the surface plate and the reading is taken with polygon in position.
- The polygon is then removed and replaced by an angle plate plus the slip gauges if necessary and a new reading is taken.
- The difference between the two sets of readings must be added or subtracted from the known angle between the particular pair of polygon faces, to give the angle of face plate.

## 4.4.2. Taper Measurement

## 4.4.2.1 Gauges for tapers

- A taper is tested by using taper plug and ring gauges. The important thing in testing a tapered job is to check the diameter at bigger end and the change of diameter per unit length. For testing the correctness of a taper, three light lines are drawn with persian blue about equidistant along the length on the (male portion) plug gauge or spindle to be tested and it is fitted in the gauge (female) and rotated once or twice. If persian blue marks do not rub off evenly, the taper is incorrect and setting must be adjusted until persian blue marks are rubbed equally all along its length.
- Taper holes can be checked by a 'Go' and 'Not Go' taper plug limit gauge as shown in Fig. 4.92. At the large end of the gauge where the large diameter of the taper hole should theoretically lie, a flat surface

is machined on the gauge on which-two lines are engraved, the distance between them is equal to the tolerance on the base distance. The line nearer to the small end represents the Go' limit and the other near the large end represents the 'Not Go' limit of the taper hole. The




Fig. 4.92.


Taper shaft under test

> Cylindrical casing

Taper ring

dimensional accuracy of the taper hole will be accepted when the taper gauge fits in the hole such that the "Not Go" limit remains outside the hole. This does not provide a positive check of the type of contact between the mating parts along the whole length of the fits. These geometrical inaccuracies can be checked by marking light lines with persian blue as explained earlier.

- Taper shafts can be checked by the reversible procedure using taper hole gauges as shown in Fig. 4.93(a, b). The solid taper sleeve gauge [Fig. 4.93(a)] has cut away portion A, on which the "Go" and "Not Go" limits are engraved. By inserting the taper shaft in the hole gauge, the small end of the taper shaft should lie between these two limits. The geometrical accuracy of the shaft can be checked by the persian blue procedure.
- The taper ring gauge [Fig. 4.93(b)] consists of a taper ring that can be placed on the taper shaft under test. A cylindrical casing is mounted on the taper ring and the position of the taper ring relative to the small end of the shaft can be checked by a gauge pin on which "Go" and 'Not Go" limits are marked. To check the geometrical accuracy of the taper shaft, more than one taper ring should be used.



(a) Solid taper sleeve gauge.





Fig. 4.93.

A positive check of the dimensional and geometrical accuracies of taper shafts can be achieved by using "May" taper gauge [Fig. 4.94). It consists of two similar side members separated by a standard central taper gauge. The taper gauge is provided with a taper work support on which the taper shaft has to rest. The height of the work support is made such that the two side members make contact with the taper shaft at two enveloping lines diametrically opposite. The two side members and the taper gauge are made separate for the universal use of the gauge and they can be screwed together. On the top surface of one of the side members the two "Go" and "Not Go" limits are provided within which the large diameter of taper shaft should lie. Geometrical



(b) Taper ring gauge.

## SCREW THREAD MEASUREMENTS

balls can be measured by means of slip gauges blocks which should be inserted without force to avoid errors. The two balls are then placed on equal columns of slip gauges of height h and the distance  $L_1$  separating the balls is also measured with slip gauges. The taper angle then be calculated as follows:

$$\tan\alpha = \frac{L_2 - L_1}{2h}$$

C. Measuring a taper hole on the sine table using internal adaptor: Fig. 4.100 shows the set-up for cylinder with suitable external diameter and a lever, hinged in the cylinder, whose magnification ratio is 1. The sine table is adjusted on one of the centres and adapter is made to contact the bottom surface of the taper surface plate. This can be ensured when the reading of the dial gauge, in contact with the adaptor, remains constant during the axial movement of the adaptor inside the taper hole. In this position, the angle made by the sine table is equal to the taper angle, angle of the component being tested.




Fig. 4.100. Set-up for measuring a taper hole on the sine table using internal adaptor.

# 4.5. SCREW THREAD MEASUREMENTS

#### 4.5.1. Introduction

A screw thread is helical ridge formed on uniform section round the curved surface. The shape of the normal section of the thread depends upon the shape of the tool which produces its groove. A screw is a male threaded piece generally cylindrical in form, but sometimes, conical (or tapered), used in most cases as a temporary fastening; less frequently used as a means of transmitting motion or power.

The screw threads are applied to many devices for various purposes as follows:

- 1. To hold parts together as in the case of fastening.
- 2. To transmit power.
- 3. To control movement as in micrometer.
- 4. To increase the effect of applied effort as in auto jack.
- 5. To convey materials as in the case of fastening.

#### 4.5.2. Classification of Threads

The threads may be classified as follows:

- 1. According to the surface on which the threads are cut:
  - (i) External threads
  - (ii) Internal threads.

for


y

The external threads are cut into the surface of a cylindrical bar.


The internal threads are cut into the surface of the cylindrical hole of a bar or cone.

- 2. According to the direction of rotation of the threaded cylinder with respect to engagement or disengagement with the other part:
  - (i) Right handed thread
  - (ii) Left handed thread.

A right handed thread is one in which the nut must be turned in a right handed direction to screw it on (Fig. 4.101(a)). A left handed thread is one in which the nut would be screwed on by turning it to the left (Fig. 4.101(b)).



(a) Right handed thread.




(b) Left handed thread.


Fig. 4.101.

- 3. According to number of starts:
  - (i) Single start threads
  - (ii) Multi-start threads.

In a piece of work it is possible to have separate and independent threads running along it. Accordingly, there are single threaded screw and multiple or multi-start threaded screw. The independent threads are called starts and we may have single start, two start, three start etc. (Fig. 4.102).

A single start threaded screw is one in which there is a movement of one thread for one complete turn round the screw or bolt. In the multi-start threaded screw there is a movement of more than one thread. In the case of double start thread, for one complete turn, the thread advances two times as if it were a single thread.








Fig. 4.102. (i) Single-start, (ii) Two-start, and (iii) Three-start threads.

Use of multi-start threads. Multi-start threads are used on those cases where rapid movement or motion is required.

Examples: Fountain-pen cap, screw press, bottles, tooth paste etc.

# 4.5.3. Elements of Screw Threads

To designate different parts of the screw threads the following terms are commonly employed:

Refer Fig. 4.103.

- 1. Major diameter. It is the largest diameter of a screw thread. It is also termed as outside or crest diameter.
- 2. Minor diameter. It is the smallest diameter of a screw thread. It is also known as root or core diameter.
- 3. Effective or pitch diameter. It is an imaginary diameter in between the major and minor diameters, and is equal to the major diameter less than an amount equal to the single depth of a thread.




Fig. 4.103. Nomenclature of a screw thread.

- 4. Axis of screw. It is the longitudinal central line through the screw.
- 5. Angle of thread. It is the angle between the two sides of a thread measured in an axial plane.
- 6. Depth of the thread. It is the angle between the crest and the root of a thread measured normal to
- 7. Thickness of the thread. It is the distance between the adjacent sides of the thread measured along or parallel to the pitch line.
- 8. Side. It is the slant surface of the thread which connects the crest with the root.
- 9. Helix angle. It is the angle made by helix of the thread at the pitch or effective diameter with the plane perpendicular to the axis.
- 10. Crest. It is top surface joining the two sides of a thread.
- 11. Root: It is the bottom surface joining the two sides of a thread.
- 12. Pitch. It is the distance from a point on one thread to the corresponding point on the next thread measured parallel to the axis of the thread. It is denoted by 'p'.
- 13. Lead. It is the distance a screw thread advances axially in one turn on a single thread screw, the lead is equal to pitch and for a double threaded screw, the lead becomes two times the pitch and so on.

Note: A screw is specified by a nominal diameter, it is the diameter of the cylindrical piece on which the threads are cut.

# 4.5.4. Specifications of a Screw Thread

To specify a screw thread the following points are given due considerations:

- 1. Shape or form of thread
- 3. Size (diameter)
- 5. Number of starts
- 7. Direction of threads

- 2. Pitch
- 4. Length
- 6. Material
- 8. Internal or external threads.



with the UNIT III Metrology = What is Metrology It is science of measurement. Purpose of meterology:

i) Establishing the units of measurement

ii) developing methods of measurement.

(iii) Analysing the accuracy of methods of Causes of Everage : Static Esexase 1) Reading error : a Parallex or optical resolution 6) Characteristic curous: It is defined as the deviation of the output of the measuring system under constant enviorenments conditions from the therotically predicted performance one from nominal performance Specification. 1 Ambient Eurae Everais aux also categories as : a Controllable Eurose b) Random Eurose

to me incument tose checking deviation from	to usifeast.
and the state of t	
b) Angle measured susument	Ruecise & Tome Yalue
(a) length measuring jest	X
(1) According to function distrument	Accurate &
* Classification of morning	
	+ sed neuch
3) fundamental	Tume value
help of mathematical calculation)	×
a) Indiscect method of measurement (with the	
1) Divert method of measurement.	Accurate 3
Classification of methods of measurement.	
0 0	Boambaat
* Factoris affecting measurement (SWIPE)	1
	out not es Twee Yolke
5) Envioument	
4) Reuson	× × ×
	Accuracy & Procession:
(1) (aliberation standards:	· Location.
	· Alignment
MoxAccusia cy Min	Pauallox
Mín	
cost	3) Stlas pressura
	a) Ambrient
ma ma	i) Calliberation
× cost	Contexollable Random
Accuracy & cost	


Scanned by CamScanner

Legal metualogy: The function of linear metrology are to ensure conservation of national standards to to grundlee & where necessary & to simplify proper accuracy to secondary standards being used in the country standards being used in the country	Vennier Callipeus & dial indicatous.  Linear measuring instrument  inside, outside, Espuing calliper, hermaphoticle callipeu, Sumface plate, angle plate, straight edge, combination gauge, radius gauge &		geometrical forms. d) Instruments for determining quality of surface finish.
Wavelength standard: The wavelength of a selected awange radiation of kappton: 86 isotope was measured a we as a basic unit of length.  differentiation between line a end standard pifference	Line Stand  as the  engreaved  end stand  as a dis	Standauds of measurement:  a) Material standard  b) wavelength standard.	H H

Scanned by CamScanner

Str no. Chauacteristic Line  1) Phuinciple wesse  4) Effect of wes  4) Effect of wes  5) Alignment can  6) Cost  7 Bradlex effect  6 Cost  7 Bradlex effect  6 Cost  1) Mechanical  2) Clecturical  3) Electornics  4) Pheumatic etc.
Line standard and standard length is expensed wessed as dist as distance beto beto two lines to a parallel forces at that to amm dimited to o con mon skill wear af ends wears at measuring surfaces only easily easily alligned alligned to not subjected to not subjected to favaller effect.  i. i
Jed Johanson's antiende antien
mical Comparents:
Scanned by CamScanner

Scanned by CamScanner




distante the distance of annature bethe two coils the current starts moving in the current showing deflection in the	phosphosous Bronz Jit meduce Blockerta po duicing band compaged to subbba band band also helps to some loss helps to
shows no deflection wherever the plunger	(3) Isimited & cale range (4) Because of ineutra, vibrations cause abbecting accustacy.
the fig. The armature is suspended on a thin steel strip beth two cails A & B.	1) less actueracy 2) due to stackning of ceretain moving pauto such as reeds are bronze band
on electrical comparator, movement of measurests contacts, is convented into electrical signals. This electrical signal is necauded by on insternment which is caliberated in terms	1) casy to operate 2) scobust & easy to handle 3) this. 4) suitable for worshop andition
S S S S S S S S S S S S S S S S S S S	for showing minute displacement of the
Mihodstone MM Coils Coils	B. Moving black is attached to Y-asim. on the Y-aum phosphorous Bronze duiving band is attached in which a duiving
A Glectrical Comparators:	If the external force is applied to a


Scanned by CamScanner


TIIN	<u>X</u>
Advantages of electuical Computations.  1). less ho of moving paints.  2) quick response with accuracy	
	Let an allowed the files through a small yet an autice of winto an intermediate thamber of then through a second anytice on it atmosphere then the intermediate
2. Volt It requires external supply	pressures Pi in the intermediate chamber will depend on the relative sizes of two
Yawiat	assifices. Since, the flow of air through two
a. Cost is high	acress them will depend on the resistance
Susces	of Oscillice of is kept constant then the
3 * Pneumatic Comparators:	in the size of oxifice Oz.
Opphice 0; porfice 02	
	1. The gauging member does not come into
Atmosphereic pressure	hence no wear a teas.
CALCON THE CALCULATION OF THE CA	usually years small pumber
Intermediate Pressure	moving pants 0 0
prieumatic a	4
the comparator will be quicken then	5. Suitable fax measuring diameters of tote

	an be divided into two parts:	
	then can be then a Rec	
	MAJOR OPERATION: All the operation reeded to generate the shape of mechanical ot.	
	tacilities hence, they are processed by basic industries.	
AW	basic operation are  () Casting (Sand Casting)  2) Fargeing  3) Rolling etc.	
	BASIC OPERATIONS: They are known as blank making process operations are some time known as founding operations. Basic process founding operations. Basic process operation are those which gives the process of the proc	i). Requires auxillary equipment. 2. Not easily partable 3. Different gauging edge for different gauging size dinfensions.
WATER OF	Classification of Operations:	tength of the hole. It tole in less tha
	UNIT I	

Scanned by CamScanner







Advantages of optical comparator:

1. High accuracy :- These Comparators have very few moving port and hence gives higher accuracy.

2. No parallax error: The scale can be read over a delim time

3. High magnification

4 Optical lever is weightlist.

Elluminated scale - since scale is illuminated, it enables suchlings to be taken irrespective of swoom eighting conditions.

Disadvantages :-


1. Depends on external electrical power supply.

2. Zustrument is bulky and supinsive

3. Due to high mignification, heat from lamp, transformers etc may cause the setting to drift


4. Dustrument should be used in dark room, therefore it is inconvenient for continuous use as viewed from exepiace.

Explain the Construction and working of Electrical Comparators.



Connected with the help of thin steel stops thes armater is also Suspended between two coils A and B. This coils are connected to Wheatshow bridge and the galvanometer of this bridge is calibrated in a manner to second the movements of plunger when the bridge is unhalanted

working " when vertical displacement is given to plunger by placing Standard which sessell the armative displacement from two its ( now the armadire is not in centre) therefore the bridge gets unbalanced and current thus through geternameter Reading is noted. Replace The standard with object again respect the same proceeders supeal "the same proceeding and note the seconding the englarence between two sceachings gives the companion thetaren standard and object. Steelment compounder have morman moving parts therefore gives wheeler stories and retailer tooking it to see the finish with more



directions in horizontal plane with cross stide plates. There is a glass plate on work table anaskich -the object is placed. There is another hollow vertical column on which applical head is mounted which can be adjusted at any position glass screen which can be rotated through an auxiliary eye piece provided on the optical head. Working - when the instrument is on and the object is placed over the glass plate of work table the stay of light to Below the work table carries the image of object to the optical head by enlarging it due to the arrangement of prism and since of reflection which can be seen through the upe piece on the Sirvere which is containing cross lines. Now in order to measure
the angle match one of the cross sine on flank of thread and it
and one of the cross sine of hastable considered as reference line and corresponding seeading of accidiary eye piece has to be noted. Then rotate the screen till the suference line comes in contact with another side of thread (Hank) . Stop violeting the screen Note down the second reading. The difference in two reading gives angle of thread. first match one of the cross line at one point of thread and note down the secaching of micrometer. Later mor the image by scaling the lateral micrometer till the corresponding point of side of the corresponding point of adjuvent Ibread is relached . Stop realating the micrometer. Note down the second reacting. The difference in two readings gires pitch of thread. For dypth of thread first match one of the cross line over the east of thread and note down the eleading of longitudinal micrometer. Then sectate the longitudinal micrometer till the stool of thread relaches the cross line which is acting as reference line. Stop Modaling longitudinal micrometer. Note down the reaching. The difference in two reactings gives depth of thread. Note - principle of tool Makin microlope & optical is available in tool makers mienscope where as there is glass struct which can be sun directly in optical profile projector. de optical profile projector the standard profile is placed on screen with which companione can be made and also deviation of object and standard can also be known.

How the major diameter of an internal thread is measured ?. The major diameter of an internal thread is measured with a thread comparator fitted with ball ended styllis of racleus less than reaction of the root of the thread to be measured. One end of styles is attacked to a floating head which is tept in contact with the plunger floating head towards the inclicator is constrained First select the standard gylindrical reference having the diameter approximately equal to the major diameter of the internal thread to be challed. Note slown the reading of dial indicator. Replace - the standard with object and engage the instrument property and note down the second reading of dial indicator. Hence the major diameter of internal thread of is now taken as = D + (R2-R1) D = diameter of standard yourdre How the minor diameter of an internal thread is measured? minor diameter of an internal thread is measured by two methods; one by wing taper parallels swond by Hallers Japer parallel method: Japer parallels are pairs of wedges having stachused and parallel outs edges. The diameter across their outer edges can be changed by sliding them over each other . Lu order to measure minor diameter first place one taper parallel on the crest of thread and then insert another brist tapor parallel till firm contact bis reached. Now stops reiching and rocesus the inter chamber werther taper parallels with the help of micrometer.
This method is suitable for small diameter of thread. Using Holling For threads bygger than 20 mm diameter precuron reality are inserted inside the thread oud proper Stippanges are insoled between the states The minor diameter is then the buyth of sop of